

COUNTY OF LOS ANGELES  
DEPARTMENT OF COUNTY ENGINEER  
BUILDING AND SAFETY DIVISION

INVESTIGATION REPORT

LOCATION OF PROBLEM 5527 Holt

LOCALITY La Jolla

DESCRIPTION OF PROBLEM

Retaining wall showing signs of  
failure - leaning and cracked  
Please check

REQUESTED BY Paul Betty PHONE 397-3810

ADDRESS Same 393-8246

RECEIVED BY L. Moore DATE 3-25-78

REFERRED TO D. O. # 7 DATE 3-29-78

REPORT OF INVESTIGATION (27" high retaining wall)  
Advised lady of the house to replace badly leaning  
wall with reinforced wall & to provide  
for drainage of retained earth.

INVESTIGATOR T. Shetye TITLE B.E.I. DATE 3-29-78

COPY SENT TO \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

REPORT PHONED TO \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

1/75